



PRACTICAL CONTROL SOLUTIONS P/L
 PH: (03) 9720 4522
 DRAWING NO: PD0007
 TITLE: P3x100
 1Phase Crouzet SSR Assy.
 ALL DIMENSIONS IN mm